## Section V - HESLTH HAZARD DATA

THRESHOLD LIMIT VALUE See II (Not Established for Product)

EFFECTS OF OVEREXPOSURE Inhalation: Anesthetic. Irritation of the respiratory tract
or acute nervous system depression characterized by headache, dizziness,
taggering gait, confusion, unconsciousness or coma. Others as noted in Sec. IX.

Skin or Eye Contact: Primary Irritation. Observe Sec. IX.

EMERGENCY AND FIRST AID PROCEDURES Inhalation: Remove from exposure. Restore breathing. Keep warm and quiet. Notify a physician. Sin Contact: Wash affected areas with water. Remove contaminated clothing. Consult a physician. Eye Contact: Flush with water for 15 minutes. Consult a physician.

Section	1/1	DEACT	rivity i	<b>ጎልፕል</b>
200000	A1	NEAL	IIAFEE	JAIA

STABILITY UNSTABLE X STABLE	CONDITIONS TO AVOID
INCOMPATABILITY (Materials to avoid)	
HAZARDOUS DECOMPOSITION PRODUCTS	<b>*</b>
Products of combustion are	hazardous.
HAZARDOUS POLYMERIZATION MAY OCCU	R WILL NOT OCCUR

## Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKENIN CASE MATERIAL IS RELEASED OR SPILLED REMOVE all sources of ignition. Avoid breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools.

WASTEDISPOSAL METHOD Dispose in accordance with local, state and federal regulations.

Incinerate in approved facility. Do not incinerate closed containers.

## Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION In outdoor or open areas use NIOSH approved mechanical filter respirator.

In restricted ventilation areas use NIOSH approved chemical-mechanical filters.

In confined areas use NIOSH approved air line type respirators or hoods.

VENTILATION Where employees may be exposed, provide general dilution or local exhaust ventilation in volume and pattern to keep TLV of hazardous ingredients in Section II below recommended (ACGIH) or regulated (OSHA) limit. Where employees will not be exposed, keep LEL in Section II below 25% of limit.

PROTECTIVE GLOVES Recommended; X Required

EVE PROTECTION Use safety eyeware designed to protect against splash of liquids.

OTHER PROTECTIVE EQUIPMENT Prevent prolonged skin contact with contaminated clothing.

## Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Do not store above 120°F. Store large quantities in buildings designed and protected for storage of flammable liquids.

OTHER PRECAUTIONS Do not take internally. Containers should be grounded when pouring. Avoid free fall of liquid in excess of a few inches. Do not sand, flame cut, braze or weld without NIOSH approved respirator or appropriate vertilation. Observe container precautionary label warnings.

In paint spray applications, chemical cartridge or, preferably, air-supplied espirators are recommended. Inhalation of isocyanates can cause allergic sensitization. Symptoms may include mucous membrane irritation, tightness of chest, irritation of respiratory tract, coughing, headache, and shortness of breath. Asthma-like attacks may follow.